Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: PIERRE 1-21H

Field Name: DOLLAR JOE Well File #: 21030

Date Incident:5/20/2016Time Incident:17:00Facility ID Number:County:WILLIAMSTwp: 155Rng: 97Sec: 21Qtr:

Location Description:

Submitted By: Shane Knuchel Received By:

Contact Person: Shane Knuchel

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 3 Barrels 3 barrels 3

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/15/2016 Clean Up Concluded: 5/22/2016

Risk Evaluation:

None

Areal Extent:

All fluid contained within dike.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Standing fluid sucked up, impacted material was removed and taken to disposal.

Wastes Disposal Location: R360 Prairie Disposal

Agencies Involved: Notified Mark Bins NDIC by phone on 5/218/2016 at 1100 AM CT.

Updates

Date: 5/23/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/connection leak, remained within diking according to the report. NDIC retains oversight.

Date: 6/6/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.